

AT 14:30:32 ON 12 MAY 2005)

FILE 'CAPLUS, WPIX, USPATFULL, USPAT2' ENTERED AT 14:31:20 ON 12 MAY 2005
E HAUG T/AU

L1 25 SEA ABB=ON PLU=ON "HAUG T"/AU
L2 107 SEA ABB=ON PLU=ON "HAUG T"/AU
L3 0 SEA ABB=ON PLU=ON "HAUG T"/AU
L4 0 SEA ABB=ON PLU=ON "HAUG T"/AU
TOTAL FOR ALL FILES
L5 132 SEA ABB=ON PLU=ON "HAUG T"/AU
E HAUG TILMAN/AU
L6 47 SEA ABB=ON PLU=ON ("HAUG TILMAN"/AU OR "HAUG TILLMANN"/AU
OR "HAUG TILMAN"/AU OR "HAUG TILMANN"/AU)
L7 0 SEA ABB=ON PLU=ON ("HAUG TILMAN"/AU OR "HAUG TILLMANN"/AU
OR "HAUG TILMAN"/AU OR "HAUG TILMANN"/AU)
L8 36 SEA ABB=ON PLU=ON ("HAUG TILLMAN"/AU OR "HAUG TILLMANN"/AU
OR "HAUG TILMAN"/AU OR "HAUG TILMANN"/AU)
L9 7 SEA ABB=ON PLU=ON ("HAUG TILLMAN"/AU OR "HAUG TILLMANN"/AU
OR "HAUG TILMAN"/AU OR "HAUG TILMANN"/AU)
TOTAL FOR ALL FILES
L10 90 SEA ABB=ON PLU=ON ("HAUG TILLMAN"/AU OR "HAUG TILLMANN"/AU
OR "HAUG TILMAN"/AU OR "HAUG TILMANN"/AU)
L11 72 SEA ABB=ON PLU=ON L1 OR L6
L12 107 SEA ABB=ON PLU=ON L2 OR L7
L13 36 SEA ABB=ON PLU=ON L3 OR L8
L14 7 SEA ABB=ON PLU=ON L4 OR L9
TOTAL FOR ALL FILES
L15 222 SEA ABB=ON PLU=ON L5 OR L10
L16 174 DUP REM L15 (48 DUPLICATES REMOVED)
L17 72 SEA L16
L18 44 SEA ABB=ON PLU=ON L17 AND CERAMIC?
L19 72 SEA L16
L20 11 SEA ABB=ON PLU=ON L19 AND CERAMIC?
L21 30 SEA L16
L22 26 SEA ABB=ON PLU=ON L21 AND CERAMIC?
L23 0 SEA L16
L24 0 SEA ABB=ON PLU=ON L23 AND CERAMIC?
TOTAL FOR ALL FILES
L25 81 SEA ABB=ON PLU=ON L16 AND CERAMIC?
L26 26 SEA ABB=ON PLU=ON L18 AND METAL?
L27 10 SEA ABB=ON PLU=ON L20 AND METAL?
L28 26 SEA ABB=ON PLU=ON L22 AND METAL?
L29 0 SEA ABB=ON PLU=ON L24 AND METAL?
TOTAL FOR ALL FILES
L30 62 SEA ABB=ON PLU=ON L25 AND METAL?
L31 6 SEA ABB=ON PLU=ON L26 AND INTERMETAL?
L32 0 SEA ABB=ON PLU=ON L27 AND INTERMETAL?
L33 12 SEA ABB=ON PLU=ON L28 AND INTERMETAL?
L34 0 SEA ABB=ON PLU=ON L29 AND INTERMETAL?
TOTAL FOR ALL FILES
L35 18 SEA ABB=ON PLU=ON L30 AND INTERMETAL?
L36 18 FOCUS L35 1-
D 1-18 BIB AB IND
E SCHEYDECKER M/AU
L37 18 SEA ABB=ON PLU=ON ("SCHEYDECKER M"/AU OR "SCHEYDECKER
MICHAAEL"/AU OR "SCHEYDECKER MICHAEL"/AU)
L38 22 SEA ABB=ON PLU=ON ("SCHEYDECKER M"/AU OR "SCHEYDECKER
MICHAAEL"/AU OR "SCHEYDECKER MICHAEL"/AU)
L39 13 SEA ABB=ON PLU=ON ("SCHEYDECKER M"/AU OR "SCHEYDECKER
MICHAAEL"/AU OR "SCHEYDECKER MICHAEL"/AU)
L40 2 SEA ABB=ON PLU=ON ("SCHEYDECKER M"/AU OR "SCHEYDECKER
MICHAAEL"/AU OR "SCHEYDECKER MICHAEL"/AU)
TOTAL FOR ALL FILES

L41 55 SEA ABB=ON PLU=ON ("SCHEYDECKER M"/AU OR "SCHEYDECKER
MICHAAEL"/AU OR "SCHEYDECKER MICHAEL"/AU)
L42 35 DUP REM L41 (20 DUPLICATES REMOVED)
L43 18 SEA L42
L44 6 SEA L36
L45 12 SEA ABB=ON PLU=ON L43 NOT L44
L46 5 SEA L42
L47 0 SEA L36
L48 5 SEA ABB=ON PLU=ON L46 NOT L47
L49 12 SEA L42
L50 12 SEA L36
L51 5 SEA ABB=ON PLU=ON L49 NOT L50
L52 0 SEA L42
L53 0 SEA L36
L54 0 SEA ABB=ON PLU=ON L52 NOT L53
TOTAL FOR ALL FILES
L55 22 SEA ABB=ON PLU=ON L42 NOT L36
D 1-22 BIB AB IND
E STORZ O/AU
L56 14 SEA ABB=ON PLU=ON ("STORZ O"/AU OR "STORZ O D"/AU OR "STORZ
OLIVER"/AU OR "STORZ OLIVER D"/AU)
L57 21 SEA ABB=ON PLU=ON ("STORZ O"/AU OR "STORZ O D"/AU OR "STORZ
OLIVER"/AU OR "STORZ OLIVER D"/AU)
L58 11 SEA ABB=ON PLU=ON ("STORZ O"/AU OR "STORZ O D"/AU OR "STORZ
OLIVER"/AU OR "STORZ OLIVER D"/AU)
L59 3 SEA ABB=ON PLU=ON ("STORZ O"/AU OR "STORZ O D"/AU OR "STORZ
OLIVER"/AU OR "STORZ OLIVER D"/AU)
TOTAL FOR ALL FILES
L60 49 SEA ABB=ON PLU=ON ("STORZ O"/AU OR "STORZ O D"/AU OR "STORZ
OLIVER"/AU OR "STORZ OLIVER D"/AU)
L61 35 DUP REM L60 (14 DUPLICATES REMOVED)
L62 14 SEA L61
L63 6 SEA L36
L64 11 SEA ABB=ON PLU=ON L62 NOT (L63 OR L45)
L65 14 SEA L61
L66 0 SEA L36
L67 14 SEA ABB=ON PLU=ON L65 NOT (L66 OR L48)
L68 7 SEA L61
L69 12 SEA L36
L70 2 SEA ABB=ON PLU=ON L68 NOT (L69 OR L51)
L71 0 SEA L61
L72 0 SEA L36
L73 0 SEA ABB=ON PLU=ON L71 NOT (L72 OR L54)
TOTAL FOR ALL FILES
L74 27 SEA ABB=ON PLU=ON L61 NOT (L36 OR L55)
D 1-27 BIB AB IND

=>

(FILE 'REGISTRY' ENTERED AT 14:57:16 ON 12 MAY 2005)

DEL HIS Y
E SILICA/CN

L1 1 SEA ABB=ON PLU=ON SILICA/CN
E TITANIA/CN
L2 1 SEA ABB=ON PLU=ON TITANIA/CN

FILE 'USPATFULL, USPAT2' ENTERED AT 14:58:41 ON 12 MAY 2005

L3 468683 SEA ABB=ON PLU=ON (L1 OR SILICA? OR (SILICON ?OXIDE?))
L4 43451 SEA ABB=ON PLU=ON (L1 OR SILICA? OR (SILICON ?OXIDE?))

TOTAL FOR ALL FILES

L5 512134 SEA ABB=ON PLU=ON (L1 OR SILICA? OR (SILICON ?OXIDE?))
L6 124149 SEA ABB=ON PLU=ON (L2 OR TITANIA? OR (TITANIUM ?OXIDE?))
L7 11423 SEA ABB=ON PLU=ON (L2 OR TITANIA? OR (TITANIUM ?OXIDE?))

TOTAL FOR ALL FILES

L8 135572 SEA ABB=ON PLU=ON (L2 OR TITANIA? OR (TITANIUM ?OXIDE?))
L9 68478 SEA ABB=ON PLU=ON L6 AND ALUMINUM?
L10 6876 SEA ABB=ON PLU=ON L7 AND ALUMINUM?

TOTAL FOR ALL FILES

L11 75354 SEA ABB=ON PLU=ON L8 AND ALUMINUM?
L12 4011 SEA ABB=ON PLU=ON 427/532000-559000/NCL
L13 360 SEA ABB=ON PLU=ON 427/532000-559000/NCL

TOTAL FOR ALL FILES

L14 4371 SEA ABB=ON PLU=ON 427/532000-559000/NCL
L15 0 SEA ABB=ON PLU=ON L12 AND INTERMEAL?
L16 0 SEA ABB=ON PLU=ON L13 AND INTERMEAL?

TOTAL FOR ALL FILES

L17 0 SEA ABB=ON PLU=ON L14 AND INTERMEAL?
L18 99 SEA ABB=ON PLU=ON L12 AND INTERMETAL?
L19 11 SEA ABB=ON PLU=ON L13 AND INTERMETAL?

TOTAL FOR ALL FILES

L20 110 SEA ABB=ON PLU=ON L14 AND INTERMETAL?
L21 589 SEA ABB=ON PLU=ON L12 AND ANNEAL?
L22 55 SEA ABB=ON PLU=ON L13 AND ANNEAL?

TOTAL FOR ALL FILES

L23 644 SEA ABB=ON PLU=ON L14 AND ANNEAL?
L24 1468 SEA ABB=ON PLU=ON L12 AND (LASER? OR LAZER?)
L25 137 SEA ABB=ON PLU=ON L13 AND (LASER? OR LAZER?)

TOTAL FOR ALL FILES

L26 1605 SEA ABB=ON PLU=ON L14 AND (LASER? OR LAZER?)
L27 23 SEA ABB=ON PLU=ON L12 AND ALUMINIDE?
L28 3 SEA ABB=ON PLU=ON L13 AND ALUMINIDE?

TOTAL FOR ALL FILES

L29 26 SEA ABB=ON PLU=ON L14 AND ALUMINIDE?
L30 26 FOCUS L29 1-
D 1-26 BIB AB IND

L31 893 SEA ABB=ON PLU=ON 427/446000/NCL OR 427/452000/NCL OR
427/453000/NCL

L32 100 SEA ABB=ON PLU=ON 427/446000/NCL OR 427/452000/NCL OR
427/453000/NCL

TOTAL FOR ALL FILES

L33 993 SEA ABB=ON PLU=ON 427/446000/NCL OR 427/452000/NCL OR
427/453000/NCL

L34 109 SEA ABB=ON PLU=ON L31 AND L9
L35 15 SEA ABB=ON PLU=ON L32 AND L10

TOTAL FOR ALL FILES

L36 124 SEA ABB=ON PLU=ON L33 AND L11
L37 31 SEA ABB=ON PLU=ON L31 AND L12

L38 5 SEA ABB=ON PLU=ON L32 AND L13

TOTAL FOR ALL FILES

L39 36 SEA ABB=ON PLU=ON L33 AND L14

L40 28 SEA ABB=ON PLU=ON L37 NOT L27
L41 4 SEA ABB=ON PLU=ON L38 NOT L28
TOTAL FOR ALL FILES
L42 32 SEA ABB=ON PLU=ON L39 NOT L29
L43 32 FOCUS L42 1-
D 1-32 BIB AB IND
L44 21 SEA ABB=ON PLU=ON L18 AND (SPRAY? (5A) (FLAME? OR THERMAL?
OR PLASMA?))
L45 3 SEA ABB=ON PLU=ON L19 AND (SPRAY? (5A) (FLAME? OR THERMAL?
OR PLASMA?))
TOTAL FOR ALL FILES
L46 24 SEA ABB=ON PLU=ON L20 AND (SPRAY? (5A) (FLAME? OR THERMAL?
OR PLASMA?))
L47 23 SEA L30
L48 28 SEA L43
L49 10 SEA ABB=ON PLU=ON L44 NOT (L47 OR L48)
L50 3 SEA L30
L51 4 SEA L43
L52 1 SEA ABB=ON PLU=ON L45 NOT (L50 OR L51)
TOTAL FOR ALL FILES
L53 11 SEA ABB=ON PLU=ON L46 NOT (L30 OR L43)
L54 11 FOCUS L53 1-
D 1-11 BIB ABIND
L55 11 FOCUS L54 1-
D 1-11 BIB AB IND

=>